
Refractometry

The refractive index is a physical property that is characteristic of a pure compound. Like a melting point, it can be used to confirm the identity of a compound, or to assess its purity, by comparison with a known (literature) value.

Principles of Refractometry

You should be familiar with the general principle of refraction: any time a light ray moves from one material to another at an angle, it changes direction. This is the principle by which a rainbow is formed. The ratio of the angle of refraction in a vacuum versus that in a material of interest is the material's index of refraction.




For practical purposes, air is normally used as a reference instead of a vacuum, since it's index of refraction is very close to (but not precisely) 1.0.

The Abbé refractometer passes light through a thin film of your liquid sample. This illuminates a reference mark, and movement of an adjustment knob to adjust the visual alignment of this mark with a reference is correlated with a calibration scale to make the measurement.


We have two types of refractometer. The older, <u>Bausch and Lomb</u> instrument is described first; the newer <u>Mark II</u> is described second.

Bausch and Lomb Refractometer




Use distilled water as a test sample to learn how to use the refractometer; its index of refraction is 1.3329 at 25°C.

Place several drops on the sample prism. (If you do not use enough sample, it will be difficult to see the mark; if you use too much it will splash out of the sample area and potentially contaminate the area.) Close the sample prism firmly, and swing the lamp up against it. Press the switch button at the back left of the instrument to illuminate the scale in the eyepiece; turn the large knob on the right of the instrument until 1.333 appears in the crosshairs:



If the scale is out of focus, readjust the eyepiece. Releasing the switch causes the view to change to the alignment mark. Center the mark in the crosshairs:



Re-illuminate the scale, and read to 5 significant figures using the top scale. The image above reads "1.4606."


To run multiple measurements, move the adjustment knob off your reading, recenter the mark, and reread the scale. Record each measurement in your notebook, along with the <u>temperature</u>.

Clean the instrument for the next person.

Mark II Refractometer

Use distilled water as a test sample to learn how to use the refractometer; its index of refraction is 1.3329 at 25°C.

The optics of this model are similar to the Bausch and Lomb instrument; application of the sample is identical:




Saura A

Apply the sample: use enogh to cover the prism, but not too much. Adjust the focus until you can see the horizontal mark (Hint: turn counterclockwise if the field is dark, clockwise if it's light.) Now, turn the control knob to center the horizontal mark in the crosshairs:



A photo showing what you will see.



Proper shadow line adjustment

Press the READ button on the front of the instrument; the refractive index will appear in the LED display.

To run multiple measurements, move the adjustment knob off your reading, recenter the mark, and reread the scale. Record each measurement in your notebook, along with the <u>temperature</u>.

Clean the instrument for the next person.

Cleaning the Instrument

Careful cleaning is critical to our continued use of these instruments. The major enemy is dust and grit. Also Kim-wipes are very abrasive and can easily scratch the prism glass. Always use cotton balls to carefully wipe away sample; then rinse with methanol and a clean cotton ball.

- Never use paper (including Kim-wipes) to clean the refractometer prisms!
- Never "scrub" the prism!

Temperature correction

Refractive index is a function of temperature, not least because of density changes in condensed materials with changes in T. A simple correction can be applied in most circumstances to allow you to report a value in the standard way: at a temperature of 25°C.

$$\eta_D^{25} = \eta_D^y - (25.0 - y)(0.00045)$$

The actual temperature of the measurement is y (in °C). η_D^{25} is the index of refraction, using the sodium D line, at 25°C; η_D^y is the index of refraction you measure at y°C. You want to report your measurement, with its 95% confidence limit, corrected to 25°C.

Back to CH362 Home Page

Last updated: 01/14/2002 Comments to <u>C. Pastorek</u>